13-2472

POPPLETON HISTORIC STUDY

Block

Lot

Address

MAG1#04247254011

170

97-105

203-219 N. Carlton Street

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

211-219

207-209


Rating Architectural		Condition			
A	Significant-save	good	fair	poor	bad
В	Quality-Indiv./groups-save	good	fair	poor	bad
C .	Important to street/groups	good	fair	poor	bad
(D)	Insignificant/detrimental	good	fair	poor	(bad)

Notable features:


Scheduled for demolition to make space for recreation facility. These houses are early workers' housing. Rundown though they are, there is an argument for their rehabilitation and re-use. Number 219 is a corner shop (or a stable?); 203-205 are garages which could go.

Environmental context:

Lots at 203-205 have already been cleared. Narrow, quiet street; all units are vacant awaiting the ball. They face the fenced yard of vacant P.S. No. 140.



B-2472 203-219 N. Carlton Street Baltimore City Sanborn Maps



Demolished

B-2472 203-219 N. Carlton Street Block 0170 Lots 097-105 Baltimore City Baltimore West Quad.

